




Software Update

TSB #	SUBJECT	DATE
SRB-R57.1	Tool Software Update R57.1	January 26, 2018
S/W VERSION[S]	TOOL[S] AFFECTED	
57.1	See Below	

OVERVIEW

This software update increases coverage, opens additional placard adjusting coverage, and improves aftermarket sensor functionality and coverage.

Feature	Exclusive	Benefit	400SD	500	300PRO	400PRO
Added Placard Coverage		2014 GMC Sierra 2500 and 3500		✓		✓
MY2018 Infiniti		Updated 2018 Infiniti model coverage for carryover vehicles: Q50, Q60, Q70, Q70L, QX30, QX60	✓	✓	✓	✓
Alligator Sens-it Coverage		Updated Alligator Sens-it coverage	✓	✓	✓	✓
2018 Infiniti QX80		New TPMS Sensor and OBD COMMS added for 2018 QX80	✓	✓	✓	✓
2018 Audi TT RS		Added coverage for 2018 Audi TT RS for Direct TPMS	✓	✓	✓	✓
2018 Genesis G80		Added sensor coverage for 2018 Genesis G80	✓	✓	✓	✓
BMW Coverage		Updated coverage for the 2016-2017 BMW X1 and relearn for the 2012-2017 BMW X3	✓	✓	✓	✓
2018 Subaru Forester		Extended coverage for the Subaru Forester through 2018	✓	✓	✓	✓
Mercedes Coverage		Updated coverage for 200-2006 Mercedes S430/S500	✓	✓	✓	✓
Mitsubishi COMMS		Improved the COMMS process for Assisted Relearn Mitsubishi Vehicles	✓	✓	✓	✓
Ford F-150 PAL Coverage		Added support for 433 PAL sensors on the 2018 Ford F-150	✓	✓	✓	✓
Mini Coverage		Updated sensor coverage for Mini	✓	✓	✓	✓
Honda		Updated OE sensor coverage for 2016-17 Honda Ridgeline. Updated coverage Honda FCX Clarity.	✓	✓	✓	✓
Kia Forte		Corrected COMMS Coverage on the 2014-2015 Kia Forte	✓	✓	✓	✓
Toyota COMMS		Bug Fix: updated Toyota COMMS	✓	✓	✓	✓
JS Steelman		Added coverage for JS Products Steelman Select programmable sensors	✓	✓	✓	✓