



## Repair Procedure

TSB #	SUBJECT		DATE
RP-159123-017	Chevrolet Malibu Limited (Fleet) vs. Chevrolet Malibu		11/20/2017
MAKE[S]	MODEL[S]	YEAR[S]	
Chevrolet	Malibu, Malibu Limited (Fleet)	2016+	
S/W VERSION[S]	TOOL[S] AFFECTED		
N/A	N/A		

### Overview:

Starting in 2015/2016, Chevrolet introduced a NEW Malibu while continuing to support fleet contracts with the existing body style. The NEW Malibu uses a 433MHz sensor, different from the previous body style. In order to insure you are configuring your tool and choosing the replacement parts correctly, please refer to the information provided below:

### Information:

**2016 Chevrolet Malibu Limited (Fleet) (Non-Turbo, Non-Hybrid)**  
(315MHz TPMS Sensors)



**2016 Chevrolet Malibu (Turbo or Hybrid)**  
(433MHz TPMS Sensors)

