



Repair Information

TSB #	SUBJECT		DATE
RP-50030-016	Activating CONTI sensors for Honda/Acura with Tech 300		May 3, 2016
MAKE[S]	MODEL[S]	YEAR[S]	
Honda/Acura	See Below	See Below	
S/W VERSION[S]	TOOL[S] AFFECTED		
	Tech 300		

Overview

Honda added Continental as a TPM supplier for MY2010 on the Crosstour. Since then, CONTI has been fitted on several models. To activate these sensors with the Tech 300 you will need to configure the LED's correctly.

Makes/Models

Crosstour	2010-Current
CR-V	2012-2013
RDX	2013-Current
ILX	2013-Current
TLX	2015-Current
NSX	2017



Position 3 GREEN

Tool Set-Up

To configure your Tech 300, use the SELECT button until the #3 position is lit GREEN. (Make sure it is ONLY position #3 that is illuminated)

