

## Tool Software Update

TSB #	SUBJECT	DATE of RELEASE
SRB-R66.0/R6.0	Tool Software Update R66.0/R6.0	9/20/2023
S/W VERSION	TOOL[S] AFFECTED	
66.0/6.0	66.0Tech300Pro/Pro C, Tech400Pro and Tech500 / 6.0 Tech450Pro, Tech550Pro, Tech600Pro and TechRITEPro	

### OVERVIEW

Feature	Description	500	300Pro	300ProC	400Pro	TRP100	450Pro	550Pro	600Pro
Coverage Update	Added Support for Sensor and OBD vehicle coverage.	✓	✓	✓	✓	✓	✓	✓	✓
Added Support for RITE-SENSOR®	Added coverage for RS-2000®.	✓	✓	✓	✓	✓	✓	✓	✓
RS-2000® Programming Messages	Added preventative measures to ensure correct sensor usage.	✓	✓	✓	✓	✓	✓	✓	✓
Increased Service Kit Options	Ability to use B-9075 as a B-9100.	✓	✓	✓	✓	✓	✓	✓	✓
Added Placard Coverage	Added Placard for Chevrolet, Ford, Ram and More.						✓	✓	✓
Updated Aftermarket Sensor Coverage	Updated coverage for Ez-Sensor®, UVS Sensor® and Redi-Sensor®.	✓	✓	✓	✓	✓	✓	✓	✓

**NOTE: Bartec USA remains committed to maintaining sensor coverage on major aftermarket sensors.**

**Multiple Software Types:** To better manage the available aftermarket sensor coverage, this release will have multiple software types for the 500 and PRO-SERIES tools. This multi-software approach will keep your Bartec tools up to date with the major aftermarket sensor suppliers.

### Tech450Pro/Tech550Pro/Tech600Pro/TechRITEPro: Required Software Type – Based on Sensors in use at your store/company.

Software Type	TPMS REPLACEMENT SENSOR TYPES								
	Bartec RITE-SENSOR® RS-1000®/RS-2000®	Bosch Quick Fit®	IntelliSens® UVS	Schrader EZ-sensor®	IntelliSens® ECS	REDI-Sensor®	Alligator Sens.it®	Dill 5001/5002/5003®	Duralast®
General Release 450/550/600	✓	✓	✓	✓	✓	✓	✓	✓	✓
TechRITEPro	✓	✓	✓	✓	✓	✓	✓		

### Tech500/300PRO/400PRO: Required Software Type – Based on Sensors in use at your store/company.

Software Type	TPMS REPLACEMENT SENSOR TYPES										
	Bartec RITE-SENSOR® RS-1000®/RS-2000®	Schrader EZ-sensor®	Bosch Quick Fit®	IntelliSens® UVS	IntelliSens® ECS	REDI-Sensor®	Dill 5001/5002	Alligator Sens.it®	QWIK®	Orange®	Duralast®
General Release	✓	✓	✓	✓	✓	✓	✓	✓			✓
Balkamp /NAPA	✓	✓	✓			✓			✓	✓	



## Tool Software Update

### Coverage Update:

Increased Coverage on the following manufactures below. To see the full list of vehicle coverage please visit:

<https://www.bartecusa.com/tpms-tool-coverage-charts>

Make	Make	Make	Make	Make
BMW	Canoo	Chevrolet	Dodge	Ferrari
Ford	GMC	Hyundai	Lincoln	Maserati
Maybach	Mazda	McLaren	Mercedes-Benz	Mitsubishi
Nissan	RAM	Totota	Volvo	

### Added Support for RS-2000® RITE-SENOSR®:

Bartec has introduced the RS-2000®, A supersession to the RS-1000®. The sensor will work with all current RS-1000® vehicles, vehicles with wheel arch initiators, and at launch Bartec will introduce 38 vehicles covered by the RS-2000®.


Make	Model	From Year	To Year	Qualifier
Acura	ILX & Hybrid	2016	2018	None
Acura	ILX & Hybrid	2019	2022	Clamp In
Acura	ILX & Hybrid	2019	2022	Snap In
Acura	Integra	2023	2024	Clamp In
Acura	Integra	2023	2024	Snap In
Acura	MDX	2007	2013	None
Acura	MDX	2014	2015	None
Acura	MDX	2016	2017	None
Acura	MDX	2018	2020	None
Acura	MDX	2022	2024	None
Acura	NSX	2016	2022	None
Acura	RDX	2007	2012	None
Acura	RDX	2013	2015	None
Acura	RDX	2016	2018	None
Acura	RDX	2019	2020	None
Acura	RDX	2021	2023	Clamp In
Acura	RDX	2021	2023	Snap In
Acura	RLX	2016	2020	None
Acura	TLX	2015	2017	None
Acura	TLX	2018	2019	None
Acura	TLX	2020	2023	None
Acura	TSX	2007	2008	None
Acura	TSX	2009	2014	None
Honda	Clarity	2008	2014	None
Honda	Odyssey	2018	2018	None
Honda	Odyssey	2019	2020	None
Honda	Odyssey	2021	2023	None
Honda	Odyssey Tour	2018	2018	None
Honda	Odyssey Tour	2019	2020	None
Honda	Passport	2019	2023	None
Honda	Pilot	2009	2015	Alloy
Honda	Pilot	2009	2015	Steel
Honda	Pilot	2016	2017	None
Honda	Pilot	2018	2023	None
Honda	Pilot Touring	2009	2015	None
Honda	Pilot Touring	2016	2017	None
Honda	Pilot Touring	2018	2023	None
Honda	Ridgeline	2017	2023	None

## Tool Software Update

### RS-2000® Programming Messages:

To prevent the user from installing the incorrect RITE-SENSOR® inside a wheel and tire during the RITE-SYNC process, Bartec has added messages to ensure the correct sensor is being used.

**Note-**Gen 1 Pro Series does not display icons.



### Increased Service Kit Options:

When replacing valves, it is important to have options. An example of that is the B-9075. It is designed to work as an alternative to the B-9100. Below are some of the MMYs this applies to.

Make	Model	Year	Qualifier	Valve	Sensor
Ford	Escape	2020-2023	None	B-9100/B-9075	RS-1000®/RS-2000®
Ford	Explorer	2020-2023	None	B-9100/B-9075	RS-1000®/RS-2000®
Ford	Interceptor Explorer	2020-2022	None	B-9100/B-9075	RS-1000®/RS-2000®
Ford	Mustang Mach E	2021-2023	None	B-9100/B-9075	RS-1000®/RS-2000®
Ford	Transit Cargo & Wagon	2020-2023	Dual- RW	B-9100/B-9075	RS-1000®/RS-2000®
Lincoln	Corsair	2020-2022	None	B-9100/B-9075	RS-1000®/RS-2000®
Mercedes-Benz	V-Class	2016-2017	None	B-9100/B-9075	RS-1000®/RS-2000®

### Added Placard Coverage:

Added Placard Coverage for the following MMYs:

Make	Model	Year	Make	Model	Year
Chevrolet	Silverado 2500	2024	Ford	F-350 SD	2023-2024
Chevrolet	Silverado 3500	2024	Ford	Maverick	2024
Chevrolet	Silverado EV	2024	GMC	Sierra 1500 Limited	2022
Ford	Bronco	2024	GMC	Sierra 2500	2024
Ford	Escape	2024	GMC	Sierra 3500	2024
Ford	Explorer	2024	Lincoln	Aviator	2024
Ford	F-150	2024	RAM	RAM 2500	2013
Ford	F-150 Lightning	2024	RAM	RAM 3500 (SRW)	2014
Ford	F-250 SD	2023-2024			

### Updated Aftermarket Sensor Coverage:

Updated aftermarket sensor coverage for Huf® (BHSens), IntelliSens UVS® and Schrader (Sensata) EZ-Sensor®.